



4 Lead Wire Stepper Motor wiring configurations

Connection	Lead Wire Connection	Lead Wire Color
4 -Lead Bipolar Series MBC or MLP Series	Phase 1 (A)	Black
	Phase 3 (/A)	Orange
	Phase 2 (B)	Red
	Phase 4 (/B)	Yellow

